



## STRUCTURAL STABILITY CERTIFICATE

This is to certify the Government Polytechnic College at Palacode in Dharmapuri District. lies in a land of 7.1 Acres in Dharmapuri District.

S. No	Name of Block / Building	Year of construction	Designed For	Existing structure	Plinth area in Sq.M		Type of Structure	Present Condition
1	Academic & Administrative Block	1990	G+1	G+1	GF	1503.28	Framed Structure	Structurally Sound
					FF	1474.02		
2	Additional Block	2012	G+1	G+1	GF	473.58	Framed Structure	Structurally Sound
					FF	498.27		
3	EEE Lab	2012	G	G	GF	193.55	Framed Structure	Structurally Sound

This is to certify that the Building is found free from visible cracks and settlements. No abnormal defects have been noticed in Administrative Block Main Building, Additional Block and EEE Lab. Hence it is certified that the above Building is structurally sound.

  
Assistant Engineer, P.W.D.,  
Technical Education Section-II,  
Dharmapuri 636 706

  
Executive Engineer P.W.D.,  
Technical Education Division  
Vellore-632 002.